L Number	Hits	Search Text	DB	Time stamp
1	534	73/37.ccls.	USPAT	2003/08/27
				14:08
2	516418	vacuum suction (negative adj pressure)	USPAT	2003/08/27 13:30
3	115	73/37.ccls. and (vacuum suction (negative adj pressure))	USPAT	2003/08/27
4	9	("3731867" "4033173" "4116348" "4215646" "4221533" "4252076"	USPAT	2003/08/27 13:57
5	16	"4261681" "4292116" "4372802").PN. 4683654.URPN.	USPAT	2003/08/27
6	33	73/37.ccls.	US-PGPUB	14:00 2003/08/27 14:09
_	414215	vacuum	USPAT	2003/08/27 13:30
-	. 8	425/137.ccls. and vacuum	USPAT	2003/08/26 17:11
-	12	("Re33237" "3172149" "3677680" "3827856" "3900278" "3964847" "4067944" "4832176" "4942008"	USPAT	2003/08/26 17:50
_	5	"5286426" "5527173" "5527174").PN. ("3371377" "3454991" "3078515" "3452399" "3303537").PN.	USPAT	2003/08/26
_	3	5645865.URPN.	USPAT	2003/08/26 17:46
-	16	3677680.URPN.	USPAT	2003/08/26
-	1	3719396.pn.	USPAT	2003/08/26
-	3	("2912282" "3120888" "3623591").PN.	USPAT	2003/08/26 17:50
-	14	3719396.URPN.	USPAT	2003/08/26 17:50
-	67	425/137.ccls.	USPAT	2003/08/26 17:51
-	0	425/137.ccls.	US-PGPUB	2003/08/27 10:17
-	0	425/137.ccls.	DERWENT	2003/08/27 10:18
-	311839		DERWENT	2003/08/27 13:30
-	12158	presence with (part object article piece)	DERWENT	2003/08/27 11:04
-		after with (molding demolding shaping forming casting reshaping)	DERWENT	2003/08/27 11:05
-	118	<pre>(presence with (part object article piece)) and (after with (molding demolding shaping forming casting reshaping))</pre>	DERWENT	2003/08/27
	5	(vacuum suction (negative adj pressure)) and ((presence with (part object article piece)) and (after with (molding demolding shaping forming casting reshaping)))	DERWENT	2003/08/27 10:23
	266840	(ejection ejecting ejected removal removed demolding demolded demold transferred transferring transfer) same (mold die tool form molded molding cast	DERWENT	2003/08/27 11:02
_	150834	casting tooling tooled forming formed) ((ejection ejecting ejected removal removed demolding demolded demold transferred transferring transfer) same (mold die tool form molded molding cast casting tooling tooled forming formed)) same (mold die tool form)	DERWENT	2003/08/27 11:03

!/

1	5573			1 2003/00/2/
l	1	<pre>(vacuum suction (negative adj pressure)) same (((ejection ejecting ejected removal</pre>	DERWENT	2003/08/27 10:26
		removed demolding demolded demold		
		transferred transferring transfer) same		
		<pre>(mold die tool form molded molding cast casting tooling tooled forming formed))</pre>		
		same (mold die tool form))		
_	135	(stop interrupt stopped stopping	DERWENT	2003/08/27
ŀ		interrupted interrupting) same ((vacuum		11:03
		suction (negative adj pressure)) same		
		(((ejection ejecting ejected removal removed demolding demolded demold		
]		transferred transferring transfer) same		
		(mold die tool form molded molding cast		
		casting tooling tooled forming formed))		
1	135	same (mold die tool form)))	DEDETEND	2003/08/27
-	133	((stop interrupt stopped stopping interrupted interrupting) same ((vacuum	DERWENT	10:49
		suction (negative adj pressure)) same		10.15
		(((ejection ejecting ejected removal		
		removed demolding demolded demold		
		transferred transferring transfer) same (mold die tool form molded molding cast		
		casting tooling tooled forming formed))		
		same (mold die tool form)))) not ((vacuum		
		suction (negative adj pressure)) and		
		((presence with (part object article piece)) and (after with (molding		
		demolding shaping forming casting		
		reshaping))))		
-	1	1976-24581X.NRAN.	DERWENT	2003/08/27
	31	425/137.ccls.	EDO. IDO.	10:46
_	31	425/13/.CCIS.	EPO; JPO; IBM TDB	2003/08/27
_	859763	(ejection ejecting ejected removal	USPAT	2003/08/27
		removed demolding demolded demold		11:03
		transferred transferring transfer) same		
		(mold die tool form molded molding cast casting tooling tooled forming formed)		
_	615161	((ejection ejecting ejected removal	USPAT	2003/08/27
		removed demolding demolded demold		11:03
		transferred transferring transfer) same		
		<pre>(mold die tool form molded molding cast casting tooling tooled forming formed))</pre>		
		same (mold die tool form)		
-	29400	(stop interrupt stopped stopping	USPAT	2003/08/27
		interrupted interrupting) same		11:04
		<pre>(((ejection ejecting ejected removal removed demolding demolded demold</pre>		
		transferred transferring transfer) same		
		(mold die tool form molded molding cast		
		casting tooling tooled forming formed))		,
_	516418	<pre>same (mold die tool form)) vacuum suction (negative adj pressure)</pre>	USPAT	2003/08/27
	310410	radam baddion (megacive ad) pressure)	USINI	11:04
_	1646	((stop interrupt stopped stopping	USPAT	2003/08/27
		interrupted interrupting) same		11:06
	1			
		(mold die tool form molded molding cast		
		casting tooling tooled forming formed))		
_	73203		USPAT	2003/08/27
			,	11:05
-	152055	after with (molding demolding shaping	USPAT	2003/08/27
_	1107		ווק מאתי	
-	119/	same (presence with (part object article	USPAI	11:06
		piece))		
- - -	73203	interrupted interrupting) same (((ejection ejecting ejected removal removed demolding demolded demold transferred transferring transfer) same (mold die tool form molded molding cast casting tooling tooled forming formed)) same (mold die tool form))) same (vacuum suction (negative adj pressure)) presence with (part object article piece) after with (molding demolding shaping forming casting reshaping) (vacuum suction (negative adj pressure))	USPAT	11:06 2003/08/27 11:05 2003/08/27 11:06 2003/08/27

-	8	<pre>((vacuum suction (negative adj pressure)) same (presence with (part object article piece))) same (after with (molding demolding shaping forming casting reshaping))</pre>	USPAT	2003/08/27
-	22	<pre>(((stop interrupt stopped stopping interrupted interrupting) same (((ejection ejecting ejected removal removed demolding demolded demold transferred transferring transfer) same (mold die tool form molded molding cast casting tooling tooled forming formed)) same (mold die tool form))) same (vacuum suction (negative adj pressure))) same (protection protecting protect)</pre>	USPAT	2003/08/27